**MEMORANDUM REPORT BRL-MR-3748** 

# BBL

ELECTRICAL IGNITION OF LGP 1846 IN A TWO-STAGE IGNITER

SELECTE MAY 16 1989

JAMES DESPIRITO JOHN KNAPTON PHILLIP REEVES

**APRIL 1989** 

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.

U.S. ARMY LABORATORY COMMAND


BALLISTIC RESEARCH LABORATORY
ABERDEEN PROVING GROUND, MARYLAND

UNCLASSIFIED	
SECTION OF THIS	PAGE

REPORT D	OCUMENTATIO				Form Approved OMB No. 0704-0188	
1a. REPORT SECURITY CLASSIFICATION Unclassified		16. RESTRICTIVE MARKINGS				
28. SECURITY CLASSIFICATION AUTHORITY		3. DISTRIBUTION / AVAILABILITY OF REPORT APPROVED FOR PUBLIC RELEASE; DISTRIBUTION				
2b. DECLASSIFICATION/DOWNGRADING SCHEDU	LÉ	UNLIMITED		KELLASE	; DISTRIBUTION	
4. PERFORMING ORGANIZATION REPORT NUMBE	R(\$)	5. MONITORING	ORGANIZATION	REPORT NU	IMBER(S)	
BRL-MR-3748				.=		
69. NAME OF PERFORMING ORGANIZATION  US Army Ballistic Rsch Lab	6b. OFFICE SYMBOL (If applicable) SLCBR-IB	7a. NAME OF M	ONITORING ORG	ANIZATION		
6c. ADDRESS (City, State, and ZIP Code)	ODODIN'ID	7b. ADDRESS (CI	ty, State, and Zi	P Code)		
Aberdeen Proving Ground, MD	21005-5066					
88. NAME OF FUNDING/SPONSORING ORGANIZATION	Bb. OFFICE SYMBOL (If applicable)	9. PROCUREMEN	T INSTRUMENT	DENTIFICAT	ION NUMBER	
Bc. ADDRESS (City, State, and ZIP Code)	<u> </u>	10. SOURCE OF	FUNDING NUMB	ERS	**	
		PROGRAM ELEMENT NO.	PROJECT NO.	TASK NO.	WORK UNIT ACCESSION NO.	
11. TITLE (include Security Classification)		<u></u>	<u> L</u>			
12. PERSONAL AUTHOR(S) DeSpirito, J.; Reeves, P.; and Kna 13a. TYPE OF REPORT MR 13b. TIME CO FROM 16. SUPPLEMENTARY NOTATION	OVERED	14. DATE OF REPO	DRT (Year, Mont	h, Day) 15	. PAGE COUNT	
17. COSATI CODES	18. SUBJECT TERMS	(Continue on reven	se if necessary a	nd identif;	by block number)	
FIELD / GROUP SUB-GROUP	.cc					
			·			
An electrically initiated, liquid propellant (LP)-based igniter was designed and tested. The igniter consisted of two stages, a 0.5 cm <sup>3</sup> precombustion chamber and a 12 cm <sup>3</sup> antechamber. A solution of potassium chloride was used in the initial tests as a LP simulant. LGP 1846 was used in all propellant tests. Preliminary results indicated that voltage breakdown (arc) may occur when the voltage across the electrode gap is greater than 500 volts. Ignition without voltage breakdown was not attained. Tests with 15 milliHenrys of inductance in the discharge circuit did not result in reliable ignition. The inductance was reduced to 2.5 mH, increasing the electrical power and absorbed energy, and reliable ignition was achieved. The amount of energy absorbed by the igniter was between 13 and 24 J in tests that resulted in ignition of the LP. This was 23 to 43 percent of the initial energy stored in the system. There was large variability in the maximum pressures attained in the igniter chambers. This was, at least in part, due to the failure of a teflon seal at the base of the precombustion chamber.  20. DISTRIBUTION/AVAILABILITY OF ABSTRACT  DUNCLASSIFIED/UNLIMITED  SAME AS RPT. DIDIC USERS  Unclassified						
220. NAME OF RESPONSIBLE INDIVIDUAL James DeSpirito		22b. TELEPHONE (301) 278-61		ode) 22c. 0 SLC	FFICE SYMBOL BR-IB-B	

#### TABLE OF CONTENTS

		Page
	LIST OF FIGURES	¥
	LIST OF TABLES	
I.	INTRODUCTION	1
II.	EXPERIMENTAL	2
III.	RESULTS AND DISCUSSION	4
IV.	SUMMARY	13
	REFERENCES	15
	DISTRIBUTION LIST	17



# LIST OF FIGURES

Figure	<u>e</u>	Page
1	Two Stage Electrical LP Igniter	. 2
2	Internal Components of Two-Stage Igniter	. 3
3	Comparison of gap voltages for Test No. KCL-01 (Solid) and Test No. 1846-01 (Dotted)	. 7
4(a)	Precombustion Chamber Pressure, Test No. 1846-13	. 11
4(b)	Antechamber Pressure, Test No. 1846-13	. 11
5(a)	Gap Current, Test No. 1846-13	. 12
5(b)	Gap Voltage, Test No. 1846-13	. 12

# LIST OF TABLES

Table		Page
1	Results of Tests with KGl Solution, Long Electrode	5
2	Results of Tests with KCl Solution, Short Electrode	5
3	Electrical Characteristics of Tests with LGP 1846, 15 mH Inductance	6
4	Electrical Characteristics of Tests with LGP 1846, 2.5 mH Inductance	8
5	Maximum Pressures in Precombustion Chamber and Antechamber	9

#### I. INTRODUCTION

The development of a liquid propellant (LP)-based ignition system for medium and large caliber regenerative liquid propellant guns (RLPGs) is a goal of the US Army's present LP program. Liquid propellant igniter test programs are being conducted at General Electric Ordnance Systems (GEOS), the Ballistic Research Laboratory (BRL), and the Ernst-Mach-Institut (EMI), West Germany. The liquid propellants being tested are the HAN-based LGP 1845 and LGP 1846.

The results of tests at the BRL on the electrical ignition of LGP 1846 have been presented at the 23rd and 24th JANNAF Combustion meetings. The igniter discussed in those papers was a single stage igniter containing approximately 2 cm³ of liquid propellant initiated by discharging a current pulse between two electrodes. The results from this igniter showed that ignition of the LP resulted from the electrochemical reaction and resistive heating produced by the current flow through the liquid rather than from the energy produced by an arc. The former process is labeled Event 1 and the latter process is labeled Event 2. The Event 1 process has also been called the formative phase. The igniter geometry and discharge circuit used at the BRL (smooth electrodes with large surface areas, relatively long gap between electrodes, and high inductance) usually limited the process to the Event 1 type. In some tests an Event 2 did occur but the current was limited to values much lower than those seen in igniters designed for an Event 2 type of ignition.

Although the results from this igniter showed that acceptable performance could be achieved, the output of the igniter venting into a 100 cm<sup>3</sup> closed chamber was not reproducible. The Ernst-Mach-Institut has achieved reproducible performance from an igniter of this design by venting the igniter into a smaller test chamber. This increases the probability of sustaining combustion of the LP that was injected, unburned, into the test chamber. The larger chamber, however, is more practical when considering application of the igniter for RLPG fixtures.

A second igniter was designed at the BRL in an attempt to achieve more reproducible performance with an Event 1 type of ignition. This igniter is called the two-stage electrical igniter. The main difference from the original igniter is that the cavity where ignition takes place is much smaller. The electrodes have smaller surface areas and less LP is involved in the ignition process. The result is that less energy will be required to ignite the propellant.

This report presents preliminary data obtained from this second igniter. Tests were performed using a salt solution (0.73 M KCl) and LGP 1846. The purpose of using the KCl solution was to become familiar with both the operation of the igniter and the electrical characteristics of the current discharge. Except for Test No. 1846-16, the LP tests were performed with the antechamber unvented and without an LP booster charge in the antechamber. Test No. 1846-16 was performed with a booster charge 1.0 cm<sup>3</sup> of LP in the antechamber and vented into a test chamber, which would be the normal igniter configuration.

#### 11. EXPERIMENTAL

The two-stage igniter is shown in Figure 1. The design is similar to the 30-mm Basic LP Igniter developed at GEOS. It consists of a precombustion chamber, an antechamber, and a vent tube for integrating into a test chamber or gun fixture. The diameter of the igniter body is 7.6 cm and the length of the assembly is about 30 cm. Figure 2 shows a close-up view of the internal section of the igniter. The precombustion chamber contains 0.5 cm of LP that is initiated by discharging a high current pulse between a pair of coaxial electrodes. The reaction in the precombustion chamber is confined by a small orifice. The combustion of the propellant in the precombustion chamber forces some unburned propellant and combustion gases into the 12 cm antechamber containing an additional LP "booster" charge. This additional propellant then burns in the antechamber and vents into a 100 cm test chamber simulating the combustion chamber of a 30-mm RLPG.




Figure 1. Two-Stage Electrical LP Igniter

The igniter components are fabricated of PH 13-8 Mo stainless steel (a precipitation hardenable stainless steel), teflon, and Macor glass ceramic. The center electrode assembly consists of the center electrode mounted in the body with teflon and Macor glass ceramic insulators. The ceramic insulator is designed to hold the stresses produced by the pressure in the precombustion chamber. An expendable teflon spacer makes up the base of the precombustion chamber and acts as a seal. The center electrode is 1.5 mm in diameter and the length of protrusion into the precombustion chamber can be varied from 3.2 mm to 7.9 mm by using additional teflon spacers. All tests were performed

with a center electrode with a hemispherical tip although square and pointed tip electrodes were available. The diameter of the precombustion chamber is 4.8 mm, making the distance between the electrodes 1.7 mm. Two precombustion chamber vent orifice diameters are available, 1.5 and 2.3 mm. A vent orifice bolt, shown in Figure 2, is used to prevent any unburned propellant that is ejected from the precombustion chamber from going directly out of the antechamber through the vent tube. This should also enhance the mixing of the combustion gases with the LP that is initially contained in the antechamber.




Figure 2. Internal Components of Two-Stage Igniter

The parameters that were measured in each test are the current and voltage versus time across the electrode gap and the pressure versus time in the precombustion chamber, the antechamber, and the test chamber. The discharge current was measured with a Pearson Model 411 Current Monitor. The voltage was determined by measuring the current through a 1000 ohm equivalent resistor in parallel with the electrode gap. The voltage was then obtained by multiplying the measured current by the known shunt resistance. This current was measured with a Pearson Model 110 Current Monitor. The current across the gap was then obtained by subtracting the current in the shunt resistance from the measured discharge current. This current is usually within one percent of the discharge current. The pressures were measured with Kistler 607C4 pressure transducers. All data was recorded on a Nicolet 4094 Digital oscilloscope. The electrical power and energy dissipated were calculated using programs available on the oscilloscope.

An Impulse Engineering Model LD-16 High Current/High Voltage Pulse Former was used to transfer the electrical energy to the igniter. The inductance, resistance, and capacitance of the pulse forming network (PFN) of this device can be varied in order to change the pulse characteristics. For the tests described in this report, the capacitance was set to 7 microFarads, the maximum available. The circuit resistance was assumed to be about 2 ohms. The initial tests were performed with an inductance of 15 milliHenries. This was reduced to 2.5 mH for the last series of tests.

There was a problem with interference from the current pulse on the pressure transducer signals during the initial tests. The interference was of the same shape as the current pulse, however it was inverted. The interference was large enough to inhibit the determination of the actual pressure in the precombustion chamber in the first several tests. The level of this interference was reduced to only a couple of percent of full scale by reducing ground loops and electromagnetic interference. Further reduction and elimination of this interference will be a goal of future testing.

#### III. RESULTS AND DISCUSSION

The first series of tests were performed with a 0.73 Molar solution of potassium chloride. The purpose of these tests was to become familiar with the operation of the igniter and check the electrical characteristics of the current discharge using a LP electrical conductivity simulator. The electrical conductance of the KCl solution and LGP 1846 are nearly the same at room temperature, approximately 0.08 ohm  $^{-1}$ -cm  $^{-1}$ . The tests were performed with the precombustion chamber venting into atmospheric pressure. The results of tests with a 7.9 mm center electrode length are shown in Table 1. In the following tables,  $\rm V_{g}$  and  $\rm E_{g}$  are the voltage and energy stored on capacitors;  $\rm I_{max}$  and  $\rm V_{max}$  are the maximum current and voltage across electrode gap;  $\rm t_{bd}$  is the time at which voltage breakdown occurs;  $\rm E_{bd}$  is the energy absorbed by the system at the point of breakdown; and  $\rm E_{ve}$  is the energy absorbed by the system at time voltage returns to zero.

Table 2 shows the results of tests with KCl solution using a 3.2 mm long center electrode. The shorter electrode increases the resistance between the electrodes, increasing the maximum gap voltage relative to that attained with the longer electrode under the same initial circuit conditions. The higher gap voltage leads to voltage breakdown occurring with lower initial stored energy (Test No. KCl-14) and at an earlier time, tbd (Test Nos. KCl-15 and KCl-16).

The results indicated that the voltage across the electrode gap would have to be kept below about 500 volts in order for voltage breakdown (Event 2) not to occur. The initial stored energy would have to be kept below 126 Joules for this discharge circuit configuration.

TABLE 1. RESULTS OF TESTS WITH KC1 SOLUTION, LONG ELECTRODE\*

Test No.	V <sub>s</sub>	E <sub>s</sub>	I <sub>max</sub>	10-90% Rise Time	Duration of Current Pulse	V <sub>max</sub>	<sup>t</sup> bd	Max Power	E <sub>bd</sub>	E <sub>Ve</sub>
	(kV)	(J)	(A)	(ms)	(ms)	(V)	(ms)	(kW)	<b>(</b> J)	<b>(</b> J)
KC1-01	3	31.5	47.8	0.395	1.240	212	N/A	9.69	N/A	5.74
KC1-02	5	87.5	82.8	0.390	1.235	392	N/A	27.6	N/A	17.1
KC1-03	6	126.	97.0	0.385	1.230	478	N/A	44.9	N/A	27.7
KC1-04	7	172.	116.	0.390	1,245	532	1.055	60.9	32.9	33,3
KC1-05	8	224.	131.	0.390	1,230	534	N/A	68.1	N/A	39.7
KC1-06	9	284.	146.	0.390	1.250	602	0.870	87.5	39.3	41,5
KC1-07	10	350.	162.	0.390	1.245	618	1.030	99.6	54.0	54.7
KC1-08	11	424.	176.	0.390	1.255	648	0.790	115.	46.4	49.7
KC1-09	12	504.	192.	0.390	1,255	674	0.660	129.	39.0	44.2
KC1-10	13	592.	207.	0.390	1.255	722	0.640	147.	41.3	47.2
KC1-11	14	686.	222.	0.395	1.255	692	0.675	149.	50.4	57.1
KC1-12	15	788.	241.	0.405	1.255	700	0.560	159.	39,3	47.6

\*Note: Volume of KCl solution was 0.5 cm<sup>3</sup>.

Length of center electrode was 7.9 mm.

Diameter of vent orifice was 2.3 mm.

Inductance in PFN was 15 mH.

N/A = no voltage breakdown

TABLE 2. RESULTS OF TESTS WITH KC1 SOLUTION, SHORT ELECTRODE\*

Test No.	V <sub>s</sub>	E <sub>s</sub>	I <sub>max</sub>	10-90% Rise Time	Duration of Current Pulse	V <sub>max</sub>	<sup>t</sup> bd	Max Power	E <sub>bd</sub>	EVe
	(kV)	(1)	(A)	(ms)	(ms)	(V)	(ms)	(kW)	<b>(</b> J)	(J)
KC1-13 KC1-14 KC1-15 KC1-16	3 5 7 9	31.5 87.5 172. 284.	46.2 80.2 115. 152.	0.365 0.390 0.420 0.445	1.235 1.270 1.265 1.260	478 602 696 688	N/A 0.685 0.505 0.475	22.1 46.7 71.3 86.4	N/A 16.4 15.4 20.0	11.7 17.7 19.8 24.8

\*Note: Volume of KCl solution was 0.5 cm<sup>3</sup>.

Length of center electrode was 3.2 mm.

Diameter of vent orifice was 2.3 mm.

Inductance in PFN was 15 mH.

N/A = no voltage breakdown

A second series of tests were performed with LGP 1846 and the same discharge circuit. These tests were performed with the igniter in a "closed chamber" configuration, i.e., the vent orifice of the antechamber was sealed by using a vent orifice bolt without holes (see Figure 2). No LP was used in the antechamber in these tests. The goal of this series of tests was to determine the performance characteristics of the first stage of the igniter. It is desired to attain a pressure of at least 5 to 10 MPa in the antechamber in order to ignite a booster charge that will be present in the igniter configuration. Table 3 shows the electrical characteristics of these tests.

TABLE 3. ELECTRICAL CHARACTERISTICS OF TESTS WITH LGP 1846, 15 mH INDUCTANCE

Test No.	V <sub>s</sub>	Orif. Size	Imax	10-90% Rise Time	Duration of Guirent Pulse	V <sub>max</sub>	<sup>t</sup> bd	Max Power	E <sub>bd</sub>	E <sub>Ve</sub>
	(kV)	(mm)	(A)	(ms)	(ms)	(V)	(ms)	(kW)	<b>(</b> J)	(J)
1846-01	3	2.3	47.2	0.385	1.265	694	0.655	30.3	6.11	7.01
1846-02	3	2.3	50.8	0.455	1.260	744	0.705	29.3	8.06	8.88
1846-03	4	2.3	66.2	0.390	1.230	792	0.920	36.0	13.2	14.0
1846-04	5	2.3	82.4	0.390	1.235	752	0.890	50.6	19.0	20.2
1846-05	5	1.5	79.6	0.365	1.230	926	0.640	70.7	14.4	22.3
1846-06	5	1.5	81.8	0.395	1.250	598	N/A	45.9	N/A	17.6
1846-07	5	2.3	82.6	0.390	1.260	918	0.530	71.0	10.9	14.7
1846-08	5	1.5	83.8	0.500	1.250	950	0.525	71.4	12.0	20.0

\*Note: Volume of LP was 0.5 cm<sup>3</sup>.

Test Nos. 1846-01 to 1846-06 performed with 7.5 mm center electrode. Test Nos. 1846-07 and 1846-08 performed with 6.4 mm center electrode.  $N/A = no \ voltage \ breakdown$ 

The igniter did not perform well in this series of tests. There was unburned LP left in antechamber when the igniter was opened after the tests. A pressure was only recorded in two tests, Nos. 1846-05 and 1846-08, in which the smaller orifice was used. The highest pressure was recorded in Test No. 1846-08, which was about 30 MPa in the precombustion chamber and 3 MPa in the antechamber. The conditions produced in the antechamber would not have led to ignition of a booster charge if it were present.

The maximum voltages attained in this series were higher than those achieved with the KCl solution at the same initial stored energy. Voltage breakdown occurred in almost every test. It is believed that the chemical reaction taking place due to the current flow occurred more rapidly in the propellant than in the KCl solution. This chemical reaction causes an insulating vapor sheath to form around the electrode, increasing the

electrical resistance of the electrode gap, resulting in a higher voltage. Figure 3 shows a comparison of the gap voltage for a test with KCl solution (Test No. KCL-01) and LGP 1846 (Test No. 1846-01) under the same conditions. The figure shows the voltage beginning to increase more rapidly at about 250 microsec for the LP and at about 650 microsec for the KCl solution. The voltage can be used as a qualitative measure of the resistance in these two tests since the gap currents were very similar. The current is not a strong function of resistance in this discharge circuit, which is indicated in Tables 1 and 2 by the small difference in maximum current between tests with the long and short center electrodes.

It was concluded that an insufficient amount of energy was being delivered to the LP in order to achieve reliable ignition with the amount of confinement that was being used. It was also obvious that an Event 1 only type of ignition would not be achieved with this configuration of the discharge circuit. It was decided that this discharge circuit would not be suitable for igniting the LP with an Event 1 alone because it is limited to 7-microFarad capacitance. Higher capacitance will be needed in order to keep the maximum voltage low and still have high enough stored energy. However, it was decided to continue testing in order to gain information and check-out the system.




Figure 3. Comparison of gap voltages for Test No. KCL-01 (Solid) and Test No. 1846-01 (Dotted).

Therefore, another series of tests was performed with the inductance in the circuit reduced from 15 to 2.5 mH. This was done in order to get more energy to the LP during the current discharge. The inductance was reduced,

rather than increasing the initial voltage, because it was not desired to increase the total stored energy. Voltage breakdown would be even more likely in these tests due to the higher gap voltage. This modification increased the energy delivered to the LP, even though the duration of the current pulse was reduced from 1.25 ms to 0.43 ms, since the maximum current was increased by a factor of three. In addition, the power was increased by a factor of three to five. The inductance was still relatively high and prevented a high current from forming when voltage breakdown occurred. Tables 4 and 5 show the electrical characteristics and the pressures recorded, respectively, for this series of tests. The small orifice was used in all tests in this series.

The results from this series of tests were much better. Ignition of the LP was achieved repeatably with 56 J of stored energy (4 kV) in the discharge circuit. The energy absorbed by the igniter,  $E_{\rm bd}$ , was measured at the point at which voltage breakdown occurred and ranged from 13 to 24 J in tests where ignition occurred. The LP did not ignite in Test No. 1846-11 with only 8.8 J of absorbed energy (14 J of stored energy). Test No. 1846-12 was a marginal case with 13.6 J of absorbed energy (31.5 J of stored energy). The pressures recorded before Test No. 1846-12 were not accurate because of interference from the current pulse. This interference was reduced to about one percent of full scale for Test No. 1846-12. This is the reason for the uncertain maximum pressures listed in Table 5 for Test Nos. 1846-09 and 1846-10.

TABLE 4. ELECTRICAL CHARACTERISTICS OF TESTS WITH LGP 1846, 2.5 mH INDUCTANCE

Test No.	V <sub>s</sub>	I <sub>max</sub>	10-90% Rise Time	Duration of Current Pulse	V <sub>max</sub>	<sup>t</sup> bd	Max Power	E <sub>bd</sub>	E <sub>Ve</sub>
	(kV)	(A)	(ms)	(ms)	(V)	(ms)	(kW)	<b>(</b> J)	<b>(</b> J)
1846-09	5	227.	0.150	0.270	1188	0.160	244.	14.2	31.6
1846-10	4	181.	0.145	0.230	1058	0.175	178.	12.9	19.4
1846-11	2	86.4	0.130	0.390	740	N/A	41.9	N/A	8.78
1846-12	3	136.	0.130	0.430	884	0.250	108.	13.6	16.3
1846-13	4	181.	0.135	0.395	1348	0.305	165.	23.9	26.7
1846-14	4	178.	0.130	0.420	1176	0.205	198.	17.0	26.9
1846-15	4	181.	0.125	0.350	1490	0.260	220.	22.9	30.5
1846-16	4	183.	0.125	0.395	1364	0.245	225.	21.5	28.3

\*Note: Length of center electrode was 6.4 mm.

Volume of LP was 0.5 cm<sup>3</sup>. Orifice size was 1.5 mm. N/A - no voltage breakdown

TABLE 5. MAXIMUM PRESSURES IN PRECOMBUSTION CHAMBER AND ANTECHAMBER\*

Test	$v_{\mathbf{s}}$	Precombustion	Chamber	Antechamber		
No.	•	Max	Rise	Max	Rise	
		Pressure	Time	Pressure	Time	
	(kV)	(MPa)	(ms)	(MPa)	(ms)	
1846-09	5	?158.		? 2.55		
1846-10	4	?199.		713.9		
1846-11	2	none		none		
1846-12	3	32.4	1.125	1.50	0.415	
1846-13	4	257.	0.185	30.4	0.705	
1846-14	4	90.8	0.365	2.06	0.860	
1846-15	4	187.	0.150	3.48	0.535	
1846-16	4	117.	0.190	1.73	0.300	

\*Note: Length of center electrode was 6.4 mm.

Volume of LP was 0.5 cm<sup>3</sup>. Orifice size was 1.5 mm

Vertical igniter orientation in Test Nos. 1846-09 to 1846-13.

Horizontal igniter orientation in Test Nos. 1846-14 to 1846-16.

Test No. 1846-16 contained 1.0 cm<sup>3</sup> of LP in antechamber. Question mark denotes uncertainty in measurement (see text).

Voltage breakdown occurred in all tests except No. 1846-11, which was at a low initial voltage. There was a small amount of pitting on the inside surface of the outer electrode due to the arc. This indicates that the arc occurred at the anode even though the highest temperature would have been at the smaller diameter center electrode, the cathode. This adds support to the theory that the electrochemical reaction caused by the current discharge through the LP may play a larger role than ohmic (resistive) heating during the Event 1 phase. The arc discharge probably occurred between the outer electrode wall and the boundary between the liquid and the gas produced at the outer electrode during Event 1. This phenomenon has been observed by Carleton et al. using high speed photography. It is likely that a vapor sheath is forming around the center electrode also, since this is where the highest temperature will be before ignition.

There was a large amount of variability in the maximum pressures recorded in Test Nos. 1846-13 to 1846-16. However, the teflon seal at the base of the precombustion chamber failed in all tests in which there was high pressure in the precombustion chamber. Therefore, the repeatability of the system can not be determined from these few tests. In addition, Test No. 1846-16 was performed with 1 cm<sup>3</sup> of LP in the antechamber and the igniter venting into a 100 cm<sup>3</sup> test chamber. The LP in the antechamber did not ignite and no pressure was recorded in the test chamber. It is believed that the failure of

the teflon seal reduced the maximum pressure produced in the antechamber, failing to ignite the LP booster charge. The failure of the teflon seal will have to be eliminated before the performance of the igniter can be fully evaluated.

Tests through No. 1846-13 were performed with the igniter in the vertical position, with the vent orifice pointing upwards. Test Nos. 1846-14, 1846-15, and 1846-16 were performed with the igniter in the horizontal position. The effect on performance cannot be determined from these few tests.

The maximum currents and rise times were repeatable. The repeatability of the voltage was not as good. The voltage signal is more dependent on the physical process taking place inside the precombustion chamber during Event 1. The formation of vapor around the electrode affects the resistance across the electrode gap which in turn affects the gap voltage. The current has already been shown not to be a strong function of resistance in this circuit.

Figures 4a and 4b show the pressures recorded in Test No. 1846-13. These were the highest pressures recorded. A pressure of 30 MPa was achieved in the antechamber in this test, Figure 4b. Tests at GE and the BRL indicate that puddles of LP can be ignited with as little as 5 to 10 MPa generated by an ignition source. Therefore, it is expected that a pressure on this order is only required to ignite a booster charge in the antechamber.

The current and voltage across the electrode gap are shown in Figures 5a and 5b, respectively. Voltage breakdown occurred at about 0.3 ms and it can be seen that the current does not increase substantially at this time. The second peak of the voltage signal is a result of the open circuit caused by the combustion of the LP.




Figure 4(a). Precombustion Chamber Pressure. Test No. 1846-13




Figure 4(b). Antechamber Pressure. Test No. 1846-13




Figure 5(a). Gap Current, Test No. 1846-13




Figure 5(b). Gap Voltage, Test No. 1846-13

#### IV. SUMMARY

It was determined from tests with both KCl solution and LGP 1846 that voltage breakdown occurs in the electrode configuration under study when the gap voltage is above about 500 to 600 volts. Ignition from the Event 1 process alone was not achieved because high enough energy cannot be attained with the present discharge circuit while keeping the gap voltage below 500 volts. A vapor sheath likely forms around the outer electrode (anode) before voltage breakdown, which occurs at that electrode. Ignition was achieved with 13 to 24 J of energy transferred to the igniter, which is 23 to 43 percent of the total stored energy. The actual amount of energy absorbed by the LP was not determined in these tests. Acceptable performance was achieved only after reducing the inductance in the discharge circuit, thereby increasing the power and energy delivered to the LP. There was a large amount of variability in maximum pressure, however, this may have been partly due to the failure of the seal at the base of the precombustion chamber.

In future tests, the seal at the base of the precombustion chamber will be modified and tests will be performed to evaluate the performance of the igniter. The effect of electrode pitting and igniter orientation will be determined. In addition, a new discharge circuit will have to be obtained in order to increase the capacitance of the system and attempt to ignite the LP without voltage breakdown occurring.

#### REFERENCES

- 1. DeSpirito, J., Knapton, J.D., Stobie, I.C., and Bensinger, B.D., "Test Data from an Electrical Liquid Propellant Igniter for Regenerative Liquid Propellant Gun Application," Proceedings of the 23rd JANNAF Combustion Meding, CPIA Publication 457, Vol. II, p. 355, October 1986.
- DeSpirito, J., Knapton, J.D., and Stobie, I.C., "Frogress Report on Electrical Ignition of Liquid Propellants for Application in Regenerative Liquid Propellant Guns," Proceedings of the 24th JANNAF Combustion Meeting, CPIA Publication 476, Vol. III, p 361, October 1987.
- 3. Giovanetti, A.J., Jardine, K.J., and DeSpirito, J., "Development of Ignition Systems for Regenerative Liquid Propellant Guns," Proceedings of the 25th JANNAF Combustion Meeting, October 1988. In publication.
- 4. Impulse Engineering, Inc., Five Science Park, New Haven, Connecticut 06511.
- 5. Carleton, F.B., Cherivan, G., Klein, N., and Weinberg, F.J., "Optical Studies of Electrical Discharge-Liquid Propellant Interactions," U.S. Army Ballistic Research Laboratory, Aberdeen Proving Ground, Md., Technical Report BRL-TR-2706, January 1986.

Copies Organization Copies Organization	
12 Administrator 5 Commander	
Defense Technical Info Center US Army Armament, Rsch,	
ATTN: DTIC-DDA Development & Engr Center	
Cameron Station ATTN: SMCAR-FSS-DA, Bldg 94	,
Alexandria, VA 22304-6145 C. Daly	
R. Kopmann	
2 Director J. Irizarry	
Defense Advanced Research M. Oetken	
Projects Agency N. Kendl	
ATTN: J. Lupo Picatinny Arsenal, NJ	
J. Richardson 07806-5000	
1400 Wilson Boulevard	
Arlington, VA 22209 5 Director	
Benet Weapons Laboratory	
2 HQDA US Army Armament, Rsch,	
(SARD-TR/B. Zimmerman, Development & Engr Center	
I. Szkrybalo) ATTN: SMCAR-CCB-DS,	
Washington, DC 20310-0001 E. Conroy A. Graham	
1 Commander SMCAR-CCB, L. Johnson	n
US Army Material Command SMCAR-CCB-S, F. Heise	
ATTN: AMCDRA-ST SMCAR-LCB-TL	
5001 Eisenhower Avenue Watervliet, NY 12189-4050	
Alexandria, VA 22333-0001	
1 Commander	
1 HQ, US Army Materiel Command US Army Armament, Munitions	
ATTN: AMCICP-AD, B. Dunetz and Chemical Command	
5001 Eisenhower Avenue ATTN: SMCAR-ESP-L	
Alexandria, VA 22333-0001 Rock Island, IL 61299-5000	
14 Cmdr, US Army Armament, Rsch, 1 Commander	
Development & Engr Center US Army Aviation Systems Cm	d
ATTN: SMCAR-TSS ATTN: AMSAV-DACL	
SMCAR-TDC (2 COPIES) 4300 Goodfellow Blvd	
SMCAR-MSI (2 COPIES) St. Louis, MO 63120-1798	
SMCAR-AEE-BR, B. Brodman	
SMCAR-AEE-B, D. Downs 1 Commander	
SMCAR-AEE-BR, W. Seals Materials Technology Lab	
A. Beardell US Army Laboratory Cmd	
SMCAR-AEE-W, N. Slagg ATTN: SLCMT-MCM-SB	
SMCAR-AEE, A. Bracuti M. Levy	
J. Lannon Watertown, MA 02172-0001	
SMCAR-FSS-D, L. Frauen	
SMCAR-FSA-S, H. Liberman	
Picatinny Arsenal, NJ07806-5000	

No. of		No.	- <del>-</del>
Copies	Organization	Copie	Organization
1	Director US Army Aviation Rach and Technology Activity Ames Research Center Moffett Field, CA 94035-1099	1	Commander US Army Tank Automotive Cmd ATTN: AMSTA-TSL Warren, MI 48397-5000
		1	Director US Army Laboratory Cmd Army Research Office ATTN: Tech Library PO Box 12211 Research Triangle Park, NC 27709-2211
1	Commander ERADCOM Technical Library ATTN: STET-L Ft. Monmouth, NJ 07703-5301	1	Director TRADOC Analysis Command ATTN: ATAA-SL White Sands Missile Range
2	Commander US Army Laboratory Cmd ATTN: SLCHD-TA-L AMSLC-DL 2800 Powder Mill Rd Adelphi, MD 20783-1145	1	NM 88002-5502  Commandant US Army Infantry School ATTN: ATSH-CD-CSO-OR Fort Benning, GA 31905-5660
1	Commander	1	Commander US Army Armament, Rsch, Development and Engr Center ATTN: SMCAR-CCS-C, T Hung Picatinny Arsenal, NJ 07806-5000
-	US Army Missile Command ATTN: AMSMI-AS Redstone Arsenal, AL 35898-5010	2	Commandant US Army Field Artillery School ATTN: ATSF-CMW ATSF-TSM-CN,
1	Commander US Army Belvoir RD&E Ctr ATTN: STRBE-WC		J. Spicer Fort Sill, OK 73503
	Tech Library (Vault) B-315 Fort Belvoir, VA 22060-5606	1	Commandant US Army Armor Center ATTN: ATSB-CD-MLD Fort Knox, KY 40121

No. of		No. o	
Copies	Organization	Copie	s Organization
1	Commander Naval Surface Weapons Center ATTN: D.A. Wilson, Code G31 Dahlgren, VA 22448-5000	_	Commandant USAFAS ATTN: ATSF-TSM-CN Fort Sill, OK 73503-5600
1	Commander Naval Surface Weapons Center ATTN: J. East, Code G33 Dahlgren, VA 22448-5000	_	Director Jet Propulsion Lab ATTN: Tech Library 4800 Oak Grove Drive Pasadena, CA 91109
2	Commander US Naval Surface Weapons Cur ATTN: O. Dengel K. Thorsted Silver Spring, MD 20902-5000	2	Director National Aeronautics and Space Administration ATTN: MS-603, Tech Lib MS-86, Dr. Povinelli
1	Commander Naval Weapons Center China Lake, CA 93555-6001		21000 Brookpark Road Lewis Research Center Cleveland, OH 44135
1	Commander Naval Ordnance Station ATTN: C. Dale Code 5251 Indian Head, MD 20640	1	Director National Aeronautics and Space Administration Manned Spacecraft Center Houston, TX 77058
1	Superintendent Naval Postgraduate School Dept of Mechanical Engr ATTN: Code 1424, Library Monterey, CA 93943	10	Central Intelligence Agency Office of Central Reference Dissemination Branch Room GE-47 HQS Washington, DC 20502
1	AFWL/SUL Kirtland AFB, NM 87117-5800	1	Central Intelligence Agency ATTN: Joseph E. Backofen HQ Room 5F22
1	Air Force Armament Lab ATTN: AFATL/DLODL Eglin AFB, FL 32542-5000	3	Washington, DC 20505  Bell Aerospace Textron
1	AFOSR/NA (L. Caveny) Bldg 410 Bolling AFB, DC 20332	J	ATTN: F. Boorady F. Picirillo A.J. Friona PO Box One Buffalo, NY 14240

No. of	Ē		No.	f	
Copies	L.	Organization	Copi	s Organization	
1	Calapa	n Corporation	1	Safety Consulting Engr	
_		Tech Library	-	ATTN: Mr. C. James Dahn	ì
	PO Box	•		5240 Pearl St	r
		o, NY 14225		Rosemont, IL 60018	
9	Genera	l Electric Ord Sys Div	1	Science Applications, In	ıc
		J. Mandzy, 0P43-220	•	ATTN: R. Edelman	,
	WTTN.	R.E. Mayer		23146 Cumorah Crest	
		H. West		Woodland Hills, CA 9136	
		W. Pasko		WOOdland Hills, OA 9130	•
		R. Pate	2	Calanas Annidastiana Int	1
			4	Science Applications Int	, · L
		I. Magoon		Corporation	
		J. Scudiere		ATTN: Dr. F. T. Phillip	.5
		Minh Luu		Dr. Fred Su	
		A. Giovanetti		10210 Campus Point Drive	i
		astics Avenue		San Diego, CA 92121	•
	Pittsi	ield, MA 01201-3698	_		_
_			1	Science Applications Int	:'1
1		l Electric Company		Corporation	
		nt Systems Department		ATTN: Norman Banks	
		D. Maher		4900 Waters Edge Drive	
	Burlin	gton, VT 05401		Suite 255	
			•	Raleigh, NC 27606	
1	IITRI				
		Library	1	Sundstrand Aviation Oper	ations
	10 W.	35th St		ATTN: Mr. Owen Briles	
	Chicag	o, IL 60616		PO Box 7202	
	_			Rockford, IL 61125	
1	Olin C	hemicals Research		·	
	ATTN:	David Gavin	1	Veritay Technology, Inc.	
	PO Box	586		ATTN: E.B. Fisher	
	Chesir	e, CT 06410-0586		4845 Millersport Highway	,
		,		PO Box 305	
2	Olin C	orporation		East Amherst, NY 14051-0	305
		Victor A. Corso			,505
		Dr. Ronald L. Dotson	1	Director	
	24 Set	ence Park	•	Applied Physics Laborato	
		ven, CT 06511		The Johns Hopkins Univ.	, L y
	.,	ve, or 00511			
				Johns Hopkins Road	
1	David A	ough Aggodut		Laurel, MD 20707	
-		ough Associates			
	ATTN:	Paul Gough			
		outh Street			
	Portsm	outh, NH 03801-5423			

No. of		No. of	
Copies	Organization	<u>Copies</u>	Organization
2	Director CPIA The Johns Hopkins Univ. ATTN: T. Christian Tech Library Johns Hopkins Road Laurel, MD 20707	] <b>A</b> ! 4:	rinceton Combustion Rsch Laboratories, Inc. PTN: N.A. Messina M. Summerfield 275 US Highway One North conmouth Junction, NJ 08852
1	U. of Illinois at Chicago ATTN: Professor Schail Murad Dept of Chemical Engr Box 4348 Chicago, IL 60680	De A' 2:	niversity of Arkansas apt of Chemical Engr PTN: J. Havens 27 Engineering Building ayetteville, AR 72701
1	U. of MD at College Park ATTN: Professor Franz Kasler Department of Chemistry College Park, MD 20742	D	niversity of Delaware epartment of Chemistry TTN: Mr. James Cronin Professor Thomas Brill Mr. Peter Spohn
1	U. of Missouri at Columbia ATTN: Professor R. Thompson Department of Chemistry Columbia, MO 65211	1 U	ewark, DE 19711  . of Texas at Austin ureau of Engineering Rach TTN: BRC EME133, Room 1.100
1	U. of Michigan ATTN: Prof. Gerard M. Faeth Dept of Aerospace Engr Ann Arbor, MI 48109-3796	1	H. Fair 0100 Burnet Road ustin, TX 78758
1	U. of Missouri at Columbia ATTN: Professor F.K. Ross Research Reactor Columbia, MO 65211		
1	U. of Missouri at Kansas City Department of Physics ATTN: Prof. R.D. Murphy 1110 East 48th Street	Aberdeen	Proving Ground
	Kansas City, MO 64110-2499	D	ir, usamsaa Attn: Ahxsy-D
1	Pennsylvania State University Dept of Mechanical Engr	_	AMXSY-MP, H. Cohen
	ATTN: Prof. K. Kuo University Park, PA 16802	C	dr, USATECOM ATTN: AMSTE-TO-F

No. of Copies Crganization Copies Organization

Cdr, CRDEC, AMCCOM
ATTN: SMCCR-RSP-A
SMCCR-MU
SMCCR-SPS-IL

Copies	Organization
1	Dr. Clive Woodley GS2 Division, Building R31 RARDE Ft. Halstead Sevenoaks, Kent TN14 7BT
	Fnoland

# USER EVALUATION SHEET/CHANGE OF ADDRESS This laboratory undertakes a continuing effort to improve the quality of the reports it publishes. Your

the report will be used.)			
How, specifically, is the repo	·	<u> </u>	
Has the information in this reperating costs avoided, or ef	eport led to any quanti fficiencies achieved, et	tative savings as far a	es man-hours or dollars saved
	ou think should be chan ht, format, etc.)	ged to improve future :	reports? (Indicate changes
	,		
BRL Report Number		Division Symbo	ol
Check here if desire	to be removed fr	om distribution :	list.
Check here for address	s change.		
Check here for address:	Organization		
	Organization		
	Organization		<del></del>
	Organization		<del></del>
	OrganizationAddress		
	Organization Address		NO POSTAGI NECESSARY IF MAILED IN THE
rector S. Army Ballistic Rescard: SLCBR-DD-T(NEI)	Organization Address FOLD AND Barch Laboratory MD 21005-5066  BUSINESS		NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATE

Director
U.S. Army Ballistic Research Laboratory
ATTN: SLCER-DD-T(NEI)
Aberdeen Proving Ground, MD 21005-9989